

1979 Cheyenne II

AIRFRAME

Total Hours 7221

ENGINES	PT6A-28	LEFT	RIGHT
Hours Since New		6675	6675
Hours Since Overhaul		3258	3258
Hours Since Hot Section		353(Cheyenne Air)	84(Southeast Turbin)

PROPS

Hours Since Overhaul 87 75

MAINTENANCE

New pilot windshield '06. New copilot windshield '96.
New cockpit windows 1/01. Event 1 & 2 due April 09

AVIONICS

FD/autopilot	King KFC-300
Radar	Bendix RDR-1100 color
Comms	King Gold Crown
Navs	King Gold Crown
Altimeter	Dual Encoding
Radar Alt	King KRA-405, 665-10
RNav	Yes
Loran	Northstar 1M
RMI	Dual
HSI	Sandel
Compass	King KPI-553 4" display
GPS	KLN-90/Garmin 530

ADDITIONAL FEATURES

Nickel Guide Vanes
Cool Start Kit
CoPilot Instruments
Auxiliary Heat

INTERIOR

Gray leather, new 1995.

EXTERIOR

Overall white w/gray, red & black stripes.